## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,971,909 B2

Page 1 of 1

DATED

: December 6, 2005

INVENTOR(S): Stewart A. Levesque and Lars R. Larsen

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## Column 5,

Line 15, should read -- although alternative securement methods may be emplooyed, as will be --.

## Column 6,

Line 54, should read -- first and second patch panel elements 102, 104. With --.

## Column 7,

Line 49, should read -- 138 are bent outwardly along elongated bar 134 and are --. Line 58, should read -- face of patch panel elements 102, 104, e.g., between aligned --.

Signed and Sealed this

Twenty-eighth Day of March, 2006

JON W. DUDAS
Director of the United States Patent and Trademark Office